

UNITED

L A B O R A T O R I E S

GENERAL INFORMATION:

United 411 SUPERSTEAM is designed to pass out of the boiler with the steam to protect all components of the steam and return system — lines, traps, tanks and pumps — against rust, corrosion and pitting.

- Safely neutralizes acidic condensate.
- Keeps radiators, convectors and unit heaters at full heating capacity.
- Prevents leaks leading to expensive repairs to lines concealed inside walls.
- Prevents corrosion of traps, returnlines and pumps.
- Saves on replacement of piping, traps, tanks and pumps.
- Low-cost insurance against costly replacements due to hidden corrosion.

DIRECTIONS FOR USE:

United 411 is best injected into the feedwater line between the final check valve and the boiler. A metering pump controlled by the feedwater pump control circuit is best. United's A603 pump is recommended, offering a range of delivery rates. **United 411** may also be added by pot feeder or into the feedwater (condensate return) tank.

INITIAL DOSAGE: Add one quart of **United 411** for every 2,000 gallons (1 litre for every 8,000 litres) of estimated boiler capacity.

MAINTENANCE DOSAGE: Feed enough **United 411** to maintain the condensate water pH in the range 7.5 - 8.5.

United 411

SUPERSTEAM

Steam and Return Line Treatment

KEEP OUT OF REACH OF CHILDREN.

CAUTION

**HARMFUL IF SWALLOWED.
SEE SIDE PANEL FOR ADDITIONAL
PRECAUTIONARY STATEMENTS.**

PRECAUCION AL USUARIO:

Si usted no puede leer Ingles, pregunte a alguien que le traduzca esta etiqueta para usted antes de uso.

UNITED LABORATORIES, INC.
320 37th Avenue • St. Charles, IL 60174
1-800-323-2594 • www.unitedlabsinc.com

CAUTION:

Contains Cyclohexylamine, (CAS #108-91-8). Excessive breathing of vapors may cause coughing, irritation of throat and mucus membranes. Chronic overexposure can cause pneumonia. Do not take internally. Avoid contact with eyes, skin or clothing. Can cause severe burns.

EMERGENCY AND FIRST AID PROCEDURES:

EYES: Flush with plenty of cool water while holding eyelids apart for at least 15 minutes. Call a physician or poison control center immediately.

SKIN: Flush with water for at least 15 minutes and call a physician or poison control center immediately.

INHALATION: Get patient to fresh air immediately. Apply CPR if needed. Call a physician or poison control center.

IF SWALLOWED: DO NOT INDUCE VOMITING. If conscious, give patient several glasses of water to dilute stomach contents. Call a physician or poison control center immediately.

An MSDS for this product is available through United's website, www.unitedlabsinc.com, providing 24 hour access. Please read the MSDS carefully and follow all directions when using or handling this product. Never reuse empty containers. Incompatible materials may adversely react.

HMIS® III CODE: 0=MINIMAL 1=SLIGHT 2=MODERATE 3=SERIOUS 4=SEVERE PERSONAL PROTECTION INDEX: Gloves and Goggles	HEALTH	3
	FLAMMABILITY	3
	PHYSICAL HAZARD	1
	PERSONAL PROTECTION	n&p