

# UNITED

LABORATORIES

## IDEAL BASE COAT APPLICATIONS:

**SHINING ARMOR** is designed for use as a protective finish on asphalt, vinyl asbestos, vinyl and other composition floors. **SHINING ARMOR** is an extraordinary resin and polymer formulation which is easy to apply and also levels. **SHINING ARMOR** is not suitable for wood floors. Coverage is approximately 1000 sq. feet per gallon.

## HOW TO USE:

1. Remove all old waxes and finishes with a good quality stripper, like United 61 Wax Stripper.
2. Rinse floor thoroughly and allow to dry completely. (A 1-2% vinegar solution in the final rinse may be used to neutralize the floor.)
3. For the best and longest-wearing results (especially on older and more porous floors), it is recommended to first apply a single coat of **SHINING ARMOR** to act as a sealer.
4. Follow the above with 2 or 3 thin, uniform coats of **SHINING ARMOR**, using a United A093 Lambswool Wax Applicator. IMPORTANT—Be sure to allow one hour drying time between coats (more if high humidity is present).
5. **SHINING ARMOR** dries to a tough, durable high sheen finish. For ultra-high gloss, **SHINING ARMOR** can be buffed.
6. Maintain the floor using United 60 NEUTRA-CLEAN or United 555 DUO-ZYME™. These products clean up dirt and will not harm the finish.

<b>HMS® III CODE:</b> 0=MINIMAL 1=SLIGHT 2=MODERATE 3=SERIOUS 4=SEVERE <b>PERSONAL PROTECTION INDEX:</b> Gloves and Goggles	HEALTH	1
	FLAMMABILITY	0
	PHYSICAL HAZARD	0
	PERSONAL PROTECTION	n&p

## United 291

# SHINING ARMOR Ultra-Solids Floor Finish

KEEP OUT OF REACH OF CHILDREN.

## CAUTION

SEE SIDE PANEL FOR ADDITIONAL  
PRECAUTIONARY STATEMENTS.

### PRECAUCION AL USARIO:

*Si usted no puede leer Ingles, pregunte a alguien que le traduzca esta etiqueta para usted antes de uso.*

**Manufactured and Sold Exclusively By:**  
**UNITED LABORATORIES, INC.**  
320 37th Avenue • St. Charles, IL 60174  
1-800-323-2594 • [www.unitedlabsinc.com](http://www.unitedlabsinc.com)

**STRIPPING: SHINING ARMOR** finished floors can be recoated up to ten times without stripping. **SHINING ARMOR** dries clear and stays clear—even in bright sun it never yellows. **SHINING ARMOR** should be removed using United 61 Wax Stripper.

Never pour the residue of **SHINING ARMOR** left in the applying pan or bucket back into the original container, as this may contaminate the unused material. **STORE CONTAINERS IN AREA PROTECTED FROM FREEZING.** Keep containers tightly closed when not being used, to prevent evaporation.

### CAUTION:

Contains Diethylene Glycol Methyl Ether (CAS # 111-77-3), Tributoxethyl phosphate (CAS # 78-51-3) and Zinc ammonium carbonate (CAS # 38714-47-5). Do not take internally.

### EMERGENCY AND FIRST AID PROCEDURES:

**EYES:** Immediately flush with plenty of water for at least 15 minutes. Get prompt medical attention.

**SKIN:** Wash with soap and plenty of water. Remove contaminated clothing and wash before reuse.

**INHALATION:** Remove to fresh air. If symptoms develop, seek immediate medical attention. If not breathing, give artificial respiration.

**INGESTION:** Get medical attention immediately. Unless advised otherwise by physician or poison center, induce vomiting by giving either syrup of ipecac followed by 2 glasses of water or by sticking finger down throat. Do not give anything by mouth if person is drowsy, unconscious or has no gag reflex.

An MSDS for this product is available through United's website, [www.unitedlabsinc.com](http://www.unitedlabsinc.com), for 24-hour access. Please read the MSDS carefully and follow all directions when using or handling this product. Never reuse empty containers. Incompatible materials may adversely react.