

UNITED

LABORATORIES

DIRECTIONS:

1. Remove all old waxes and finishes with a good quality stripper, United 61 Wax Stripper.
2. Rinse floor thoroughly and allow to dry completely. (A 1-2% vinegar solution in the final rinse may be used to neutralize the floor.)
3. For the best and longest-wearing results (especially on older and more porous floors), it is recommended to first apply a single coat of **United 791** to act as a sealer.
4. Follow the above with 2 or 3 thin, uniform coats of **United 791**, using a United A093 Lambswool Wax Applicator. **United 791** covers approximately 1200 to 1500 square feet per gallon. **IMPORTANT**—Be sure to allow one hour drying time between coats (more if high humidity is present).
5. **United 791** dries to a tough, durable high sheen finish. For ultra-high gloss, **United 791 SUPER SHINE** can be buffed.
6. Maintain the floor using United 60 Concentrate; it cleans up dirt and absolutely will not harm the finish. **STRIPPING: United 791** finished floors can be recoated up to ten times without stripping. **SUPER SHINE** dries clear and stays clear—even in bright sun it never yellows. **United 791** should be removed using United 61 Wax Stripper.

Never pour the residue left in the applying pan or bucket back into the original container, as this may contaminate the unused material. **STORE CONTAINERS IN AREA PROTECTED FROM FREEZING.** Keep containers tightly closed when not being used, to prevent evaporation.

NOTE: United 791 is ideal for use with the high-speed buffers.

United 791

SUPER SHINE Floor Finish

KEEP OUT OF REACH OF CHILDREN.

CAUTION

SEE SIDE PANEL FOR ADDITIONAL PRECAUTIONARY STATEMENTS.

PRECAUCION AL USUARIO:

Si usted no puede leer Ingles, pregunte a alguien que le traduzca esta etiqueta para usted antes de uso.

Manufactured and Sold Exclusively By:
UNITED LABORATORIES, INC.
320 37th Avenue • St. Charles, IL 60174
1-800-323-2594 • www.unitedlabsinc.com

CAUTION:

Contains Diethylene glycol methyl ether (CAS# 111-77-3), Tributyoxyethyl phosphate (CAS# 78-51-3) and Zinc ammonium carbonate (CAS# 38714-47-5). Do not take internally. Prolonged skin contact may cause irritation.

EMERGENCY AND FIRST AID PROCEDURES:

EYES: Immediately flush with plenty of water for at least 15 minutes. Get prompt medical attention.

SKIN: Wash with soap and plenty of water. Wash clothing before reuse.

INHALATION: Remove to fresh air. If symptoms develop, seek medical attention. If not breathing, give artificial respiration.

INGESTION: Get medical attention immediately. Unless advised otherwise by physician or poison center, induce vomiting by giving either syrup of ipecac followed by 2 glasses of water or by sticking finger down throat. Do not give anything by mouth if person is drowsy, unconscious or has no gag reflex.

An MSDS for this product is available through United's website, www.unitedlabsinc.com, for 24-hour access. Please read the MSDS carefully and follow all directions when using or handling this product. Never reuse empty containers. Incompatible materials may adversely react.

| | | |
|---|---------------------|-----|
| HMIS® III CODE: 0=MINIMAL 1=SLIGHT 2=MODERATE 3=SERIOUS 4=SEVERE PERSONAL PROTECTION INDEX: Gloves and Goggles | HEALTH | 1 |
| | FLAMMABILITY | 0 |
| | PHYSICAL HAZARD | 0 |
| | PERSONAL PROTECTION | n&p |